

**City of Watauga's**  
**Open Records Request**

**Start date**  
**Month of April, 2017**

Case Type	Case Description	Initial Inspection Date	Short Address
Address	The address is required to be visible at the location.	04/11/2017	6057 Hillglen Dr.
<b>Address</b>			
Total Cases:		<b>1</b>	
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/05/2017	6213 Cascade Cir.
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/06/2017	6945 Yorkston
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/06/2017	6913 Betsy Ross
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/12/2017	6044 Robin Dr.
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/17/2017	6809 Bennington Dr.
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/19/2017	6505 Jerri Lynn Dr.
Exterior Property	All rotted wood must be repaired and made	04/19/2017	6621 Jerri Lynn Dr.

	weather resistant. All chipping paint must be repaired and painted.		
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/19/2017	6625 Constitution Dr.
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/20/2017	6324 Patsy Ln.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/20/2017	7208 Echo Hill Dr.
Exterior Property	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	04/25/2017	5913 Nanci Dr.
Exterior Property	there must be no broken windows on property, (Garage)	04/25/2017	6433 Heather Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted		6917 Wooddale Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/25/2017	6917 Wooddale Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/25/2017	7004 Lyndale Dr.

Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/25/2017	6716 Lyndale Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/28/2017	6621 Emily Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/28/2017	5625 Main St.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/28/2017	6054 Fleming Dr.
Exterior Property	All rotting wood must be replaced or repaired and made weather resistant. Any exposed wood must be painted or made weather resistant. Peeling, flaking and chipped paint shall be eliminated and surfaces repainted	04/28/2017	6058 Fleming Dr.
<b>Exterior Property</b>			
Total Cases:		<b>20</b>	
Vacant Property High Weeds	Grass must remain under 12 inches at all times in the front and back yard, as well as be edged and trimmed around sidewalks, fence, etc.	04/10/2017	5921 Oak Hill Rd.

Grass may NOT be blown into street or left on the sidewalk. Grass must be disposed of properly. This is an annual notice, when found in violation a citation may be issued without notice.

Grass must remain under 12 inches at all times in the front and back yard, as well as be edged and trimmed around sidewalks, fence, etc. Grass may NOT be blown into street or left on the sidewalk. Grass must be disposed of properly. This is an annual notice, when found in violation a citation may be issued without notice.

Vacant Property High Weeds

04/12/2017

5928 Nanci Dr.

**Vacant Property High Weeds**

Total Cases: 2

Vacant Property Registration

04/25/2017

5717 Bonnie Dr.

**Vacant Property Registration**

Total Cases: 1

<b>TOTALS:</b>	Total Cases:	<b>24</b>
----------------	--------------	-----------