

**City of Watauga's
Open Records Request**

**Start date
Month of June, 2018**

Case Type	Case Description	Initial Inspection Date	Short Address
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	06/13/2018	6200 Cascade Ct.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	06/15/2018	5748 Bonnie Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	06/15/2018	5724 Bonnie Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	06/15/2018	5725 Bonnie Dr.
Exterior Structure	All rotted wood must be repaired and made weather resistant. All chipping paint must be repaired and painted.	06/22/2018	6516 Summit Ridge Dr.
Exterior Structure			
Total Cases:	5		
Hazardous Disposal of Waste		06/21/2018	6592 Old Mill Cir.
Hazardous Disposal of Waste	RVs may not be stored in the street at any time. RVs must be parked behind property line on approved hard surface (concrete, asphalt). They are allowed in the street for loading and unloading purposes only, for a max of 3 hours.	06/27/2018	5932 Hickoryhill Rd.
Hazardous Disposal of Waste	Hazardous waste my not be disposed of in the street curb line.	06/29/2018	5932 Hickoryhill Rd.

Hazardous Disposal of Waste

Total Cases: **3**

Vacant Property Swimming Pool Maintenance	Swimming pool must remain clean and clear to be able to see through the water as well as avoid mosquito breeding.	06/01/2018	6837 Lyndale Dr.
---	---	------------	------------------

Vacant Property Swimming Pool Maintenance

Total Cases: **1**

TOTALS:	Total Cases:	9
----------------	--------------	----------